




University of Southern California Health Sciences Campus
CONSTRUCTION PROJECTS

- CAPITAL CONSTRUCTION DEVELOPMENT PROJECTS
- FACILITIES MANAGEMENT SERVICES MAINTENANCE PROJECTS
- UTILITIES PROJECTS
- ITS PROJECTS
- ▨ CURRENT SITE CONSTRAINTS
- ▭ PLANNED SITE CONSTRAINTS

Construction						
#	BLDG	PROJECT	START	END	DESCRIPTION	CONTACT
HSC Capital Construction						
01	BMT	485297	12/19/2022	1/2/2023	401 Conference Room Refresh	Eric Duran (323) 442-0161
02	DOH	472587	12/15/2022	10/23/2023	Building Rehabilitation Phase 1	Walt Stahl (916) 288-8548
03	HMR	319713	8/16/2021	2/10/2023	DFM HSC High Rise Roof Access Compliance	Shouning Li (213) 740-3068
04	NOR	321112	8/28/2021	12/30/2022	2nd, 4th Floor DFM HVAC Test, Adjust, & Balance	Paul Risko (323) 442-1544
05	NOR	210878	11/19/2022	3/31/2023	7th Floor Emergency Eye Wash/Shower Stations	Paul Risko (323) 442-1544
06	NRT	319713	8/16/2021	2/10/2023	DFM HSC High Rise Roof Access Compliance	Shouning Li (213) 740-3068
07	PGH	443775	12/5/2022	1/6/2023	Demolish Building and Fence Lot	Hector Puga -
08	PSC	484167	12/1/2022	12/30/2022	206 & 209 Office Refresh	Eric Duran (323) 442-0161
09	PSC	319713	8/16/2021	2/10/2023	DFM HSC High Rise Roof Access Compliance	Shouning Li (213) 740-3068
10	UNH	224096	7/11/2022	1/12/2023	1002, 1004, Lobby, Restroom Refresh	Jing Gung Cheng (323) 442-2070
HSC Maintenance						
a	CSA	230263	<null>	<null>	DFM Pure Water System Replacement	Bill Cadieux (949) 616-8657
b	EVH	235449	12/7/2021	1/20/2023	DFM Generator Replacement	Laura Svoboda -
c	HC4	334596	11/07/2022	4/27/2023	DFM Chilled Water System	Jing Gung Cheng (323) 442-2070
d	MMR	342907	11/14/2022	<null>	DFM Pure Water System Project	Bill Cadieux (949) 616-8657
e	NOR	166724	1/17/2022	7/31/2023	DFM Replace ATS 1-5 and 6-Power Switchgear	Paul Risko (323) 442-1544
f	NOR	PR053175	10/25/2021	2/15/2023	DFM AHU 1-2 Replacement	Walt Stahl (916) 288-8548
g	NTT	PR052787	8/26/2021	3/31/2023	DFM AHU 4-7 Replacement	Walt Stahl (916) 288-8548
h	PSC	321364	1/20/2022	2/24/2023	DFM Generator GEN-B Replacement	Roberto Villamar (213) 326-3292